

Weekly Construction Status Update

Farmington Public Schools

Alameda Early Childhood Education Center

Friday, January 10, 2020

Progress Overview



Overall view of addition: S/E corner (left), N/W Corner (right).

Progress Overview



Classroom entry soffits.

Progress Overview



Plumbing, mechanical, electrical pipe and systems installed above ceiling.

Progress Overview

Acoustical ceiling
installation
progressing.



Two Week Look Ahead

- Interior rough plumbing, mechanical and electrical.
- Acoustical drop ceiling installation.
- Remove and replace chiller.
- Continue w/ building addition tie-in to existing school.