

Weekly Construction Status Update

Farmington Public Schools

Alameda Early Childhood Education Center

Friday, January 17, 2020

Progress Overview



View of classroom entry soffits

Progress Overview



Gross Motor Room curtain wall framing installed.

Progress Overview



Rough electrical and plumbing installation in progress.

Progress Overview

Welding of mechanical
pipe systems, above
ceiling.



Two Week Look Ahead

- Interior rough plumbing, mechanical and electrical.
- Acoustical drop ceiling installation.
- Interior casework installation.
- Continue w/ building addition tie-in to existing school.