

Weekly Construction Status Update

Farmington Public Schools

Alameda Early Childhood Education Center

Monday, March 9, 2020

Progress Overview



Generator and MSB enclosure equipment in place.

Progress Overview



New water heater install in progress (existing water heater to be replaced in background).

Progress Overview



Casework and marker/tack boards installed.

Progress Overview

View of S/E corner of new addition.



Two Week Look Ahead

- Interior painting.
- Acoustical drop ceiling installation.
- Interior door installation.
- LVT and ceramic floor tile installation.