

Weekly Construction Status Update

Farmington Public Schools

Alameda Early Childhood Education Center

Friday, March 13, 2020

Progress Overview



Classroom (lft) and Science/Media Center (rt) Casework.

Progress Overview



Bathroom tile floors and door threshold installed.

Progress Overview



Mechanical piping and electrical lighting/devices continues.

Progress Overview

West exterior view of the addition.



Two Week Look Ahead

- Electrical lighting and device installation.
- Classroom flooring.
- Interior painting .
- Final mechanical/HVAC finishes.