Weekly Construction Status Update

Farmington Public Schools

Alameda Early Childhood Education Center

Friday, June 26, 2020









Addition: Flooring for classroom and offices in progress.







Addition: Gross Motor Room Bench Installation.









New concrete planter: forming of walls (left), finish product (right).





Renovation: New CMU walls, with block filler.







Two Week Look Ahead

- Complete demolition.
- Continue masonry wall install in renovation.
- Rough plumbing, mechanical, electrical –
 Renovation area.
- Site piping install and parking lot preparations.



