Weekly Construction Status Update

Farmington Public Schools

Alameda Early Childhood Education Center

Friday, June 12, 2020









Demolition of Zone "B" classrooms and corridors.







Gross Motor Room ceiling installation underway.










Boiler and classroom radiant heat panel installation continues.





Demolition of boys gang bathroom underway.







Two Week Look Ahead

- Continue building renovation demolition.
- Exterior wall panel installation of addition.
- CMU wall installation, in corridors.
- Final mechanical/HVAC, electric finishes for addition.



