Weekly Construction Status Update

Farmington Public Schools

Alameda Early Childhood Education Center

Friday, October 25, 2019









HVAC and electrical trades in progress throughout the addition.







Ironworkers installing joist and metal decking.









Interior walls for classrooms in progress: View of entry and back of in-room bathrooms.





Masonry veneer underway.







Two Week Look Ahead

- Interior rough plumbing, mechanical and electrical.
- Interior masonry walls.
- Face brick installation.
- Install roof membrane and accessories.



