

Weekly Construction Status Update

Farmington Public Schools

Alameda Early Childhood Education Center

Monday, November 25,
2019

Progress Overview



Rough plumbing, HVAC and electrical continues.

Progress Overview



Classroom and Media Center walls being constructed.

Progress Overview



Building is weather tight for the fall/winter.

Progress Overview

Interior joint
sealing in
progress.



Two Week Look Ahead

- Interior rough plumbing, mechanical and electrical.
- Interior masonry walls.
- Exterior frames, glass installation.
- Prep for prime painting.