

Weekly Construction Status Update

Farmington Public Schools

Alameda Early Childhood Education Center

Friday, December 6, 2019

Progress Overview



Concrete pads for new electrical service and generator.

Progress Overview



New office for building addition.

Progress Overview



Window installation underway.

Progress Overview

Prime paint has begun.



Two Week Look Ahead

- Interior rough plumbing, mechanical and electrical.
- Paint interior walls.
- Framing and installation of drywall ceilings and soffits.
- Acoustical ceiling installation.