

Farmington Public Schools

Alameda Early Childhood Education Center

Friday, December 13, 2019

Progress Overview



Plumbing, mechanical and electrical installation in progress.

Progress Overview



View of building addition,
looking northwest.

Progress Overview



Above ceiling piping and ceiling framing underway.

Progress Overview

Front
Entry/Office
window
installation.



Two Week Look Ahead

- Interior rough plumbing, mechanical and electrical.
- Canopy installation.
- Framing and installation of drywall ceilings and soffits.
- Building addition tie-in to existing school.