

Weekly Construction Status Update

Farmington Public Schools

Alameda Early Childhood Education Center

Friday, December 27, 2019

Progress Overview



Canopy installed along front entry of addition – West Elevation.

Progress Overview



Classroom view of exterior.

Progress Overview



Work progressing on building addition tie-in to existing school.

Progress Overview

Metal stud framing and rough electrical (lighting) for classroom soffits.



Two Week Look Ahead

- Interior rough plumbing, mechanical and electrical.
- Acoustical drop ceiling installation.
- Framing and installation of drywall ceilings and soffits.
- Continue w/ building addition tie-in to existing school.