

Highmeadow Elementary 2019 Renovations - Progress Report

Progress Overview



- First picture is the hallway at the west entrance.
- Second is one of three classrooms on that hallway that is underway.

Progress Overview



- On the left is the current demo state in the computer lab.
- On the right is the demo within the library.

Progress Overview



- In room 074 (Existing Storage) we plan to remove the floor in here, based on it's current condition.



Progress Overview

- Extra Images



Room 063



Room 059



Room 060

Two Week Look Ahead

Week of May 27th

- Begin painting

Week of June 3rd

- Setup onsite review for roofing with architect and contractor
- Painting ongoing