



Farmington Public Schools

North Farmington High School

April 19, 2018



Project Overview



The old catwalk has been removed and the new one is being installed. It was difficult to walk along the old catwalk due to the confined height and width; the new one provides 6' head clearance and 6' width, allowing much improved access.

Project Overview



The drywall work in the auditorium is well underway along with the underground electrical work for the new audio/visual control from the new control booth and directors booth locations.

Project Overview

The new auditorium entrance has also been constructed providing a lobby which will buffer sound from the auditorium as well as the exterior entrance area.



Project Overview



In the media center the café area is nearing completion, flooring is underway and accent colors have been added to various walls.

Project Overview

Flooring and accent colors are being installed in the main office area as well.



Project Overview



The temporary construction partition has been removed from the entrance lobby area revealing the new office wall.

Project Overview



The unit heaters throughout the building are being replaced and the lighting in the auxiliary gym and auto shop was replaced over winter break.