

Weekly Construction Status Update

Farmington Public Schools

Alameda Early Childhood Education Center

Friday, August 30, 2019

Progress Overview



Masons making excellent progress on CMU walls.

Progress Overview



Corridor bathroom plumbing, just outside of the Media Center.

Progress Overview



Curved exterior wall shown for the Gross Motor Room.

Progress Overview

Looking north
from the existing
school at the
overall addition.



Two Week Look Ahead

- Continue with masonry walls.
- Continue with under slab and wall installation of mechanical, electrical, plumbing sleeves/piping/rough-in's.
- Prep for concrete floor slab placement.