

Weekly Construction Status Update

Farmington Public Schools

Alameda Early Childhood Education Center

Friday, September 6, 2019

Progress Overview



Masonry walls continue going up.

Progress Overview



Concrete slug bases for
exterior parking lot
lighting.

Progress Overview



North wall of addition: Wall is ready to accept face brick.

Progress Overview

Looking west at
overall addition
from temporary
playground.



Two Week Look Ahead

- Continue with masonry walls.
- Continue with under slab and wall installation of mechanical, electrical, plumbing sleeves/piping/rough-in's.
- Begin concrete floor slab placement.