

Weekly Construction Status Update

Farmington Public Schools

Alameda Early Childhood Education Center

Friday, September 20,
2019

Progress Overview



Underground plumbing and electrical installation.

Progress Overview



View of addition, looking north.

Progress Overview



North entry of new addition; Before & After
CMU installation.

Progress Overview

New,
replacement
exhaust fans for
existing school.



Two Week Look Ahead

- Continue with masonry walls.
- Set light pole bases/exterior lighting.
- Continue concrete floor slab placement.
- Begin face brick installation.
- Set addition joists and decking.