

Weekly Construction Status Update

Farmington Public Schools

Alameda Early Childhood Education Center

Friday, November 8, 2019

Progress Overview



Prep floors for concrete slab placement.

Progress Overview



Classroom vertical unit ventilators delivered.

Progress Overview



Rough mechanical, electrical and plumbing in progress.

Progress Overview

Concrete floor
slab at Gross
Motor Room.



Two Week Look Ahead

- Interior rough plumbing, mechanical and electrical.
- Interior masonry walls.
- Face brick installation.
- Prep for prime painting.