


## North Farmington High School

### 2019 Renovations

-

### Progress Report

# Progress Overview



- Two separate views from the boys locker room getting redone. Tile flooring is in throughout the locker room.

# Progress Overview



- Same spot as last slide, but for the girls locker room. Flooring also finished here too.



# Progress Overview



- Work is progressing nicely in the new classroom and it has been disconnected from the locker rooms.

# Progress Overview



- Flooring is still currently being removed in a handful of the remaining science rooms.





# Progress Overview



- Continuing to chip away and scrape at any residue left over in an attempt to make it as smooth as possible up front.

# Progress Overview




- The casework/storage in the musical hall has been moved back in.





# Progress Overview



- Stairway in music storage room has been painted, walls should be painted next