

Warner Middle School

2019 Renovations

-

July 30th, 2019

Progress Overview




- Work is still being done outside, no crazy changes from last week.

Progress Overview



- Small dropdown is completed and the showcase spots are truly visible now.

Progress Overview



- Ceiling grid is in so expect ceiling tile soon after everything thing is finished above the grid.

Progress Overview



- A brick face has been put on the handful of square columns and this wall pictured, very nice look.




Progress Overview



- The vast majority of classrooms now have flooring down.

Progress Overview



- Including the new addition front office's flooring.

Progress Overview



- Library has walls down as of now to make room for the new folding glass wall system on each side.

Progress Overview



- North facing wall in NE corner has been painted and actually looks like it belongs there.

Progress Overview



- Many of the door/window frames around the school have been painted, the others are ready to be.



Progress Overview



- Kitchen work is still going strong, wall tiling is now up along with other progressions.

